

2013 ANNUAL REPORT

TOWN OF WINTERVILLE COLLECTION SYSTEM

PERMIT: WQCS00117

The Clean Water Act of 1999 requires wastewater collection systems to provide an annual report to their customers. This report summarizes the performance of the Town of Winterville's wastewater collection system for the 12-month period from January 1, 2013 to December 31, 2013.

The Town of Winterville operates a wastewater collection system under permit WQCS00117, issued by the Division of Water Quality, NC Department of Environment and Natural Resources. The permit was issued on March 4, 2013 and is valid from June 1, 2013 until March 31, 2021. This system consists of approximately 47.54 miles of gravity sewer, approximately 1.3 miles of pressure sewer, approximately 11.9 miles of force main, 23 duplex pump stations, 62 simplex pump stations that discharge to a pressure sewer and serve a single building, and all the associated piping, valves, and appurtenances necessary to operate a wastewater collection system for the Town of Winterville.

Wastewater collected by this system is pumped to the Contentnea Metropolitan Sewerage District (CMSD) wastewater treatment plant in Grifton via a fourteen inch diameter force main, where it is treated prior to discharge into Contentnea Creek. CMSD operates under permit number NC0032077.

During the year 2013, the Town of Winterville system collected 276,544,000 gallons of wastewater, an average of 757,654 gallons per day. The Town had one Sanitary Sewer Overflow (SSO) of approximately 1,680 gallons on November 3, 2013. The volume of this spill was approximately 0.000006% of the total volume of wastewater collected by the Town. Our 23 pump stations are visited and inspected four to five times a week to ensure that they are operating correctly. Each of the 23 pumping stations is equipped with two pumps that alternate in operation and provide redundancy for emergencies. The Town also has backup generators and by-pass pumps which can quickly be mobilized to the lift stations in case of a power failure.

Over the last 12 months, many upgrades have been made to our existing lift stations including replacing pumps and impellers, replacing check valves, and updating our telemetry system. These upgrades should help improve the efficiency and reliability of our lift stations. The Town has also continued working with its consulting Engineer on a systemwide comprehensive sanitary sewer evaluation. This evaluation will help point out deficiencies and problems with our collection system, mainly including inflow and infiltration problems. By eliminating these issues, the Town will be better prepared to handle large flows during heavy rain events and prevent future SSO's.

To help reduce the grease build up in the town's collection system each lift station is cleaned once a quarter. In addition, a minimum of 10 percent of the gravity sewer mains are cleaned per

year. Due to the systemwide evaluation, a much greater portion of the gravity system has been cleaned this year.

Hard copies of this report are available at Winterville Town Hall located at 2571 Railroad Street, as well as online at www.wintervillenc.com. Should you have any questions, please contact the Public Works Department, by mail at P.O.Box 1459, Winterville, N.C. 28590; by telephone at 252.215.2427; or visit us at www.wintervillenc.com.

This report is accurate and complete to the best of my knowledge.

Travis Welborn, PE
Public Works Director
Town of Winterville